	Туре	Hits	DBs	Time Stamp	Search Text	Comments	Error Definitio
1	IS&R	35	USPAT; US-PGPUB; EPO; JPO; DERWENT		(("200300 66976") or ("2002013 0278") or ("6534775") or ("6534775") or ("6489622") or ("6326631") or ("6111260") or ("6039847") or ("5925886") or ("5925886") or ("5780862") or ("5780862") or ("5780862") or ("5748360") or ("5748360") or ("5420437") or ("5365070") or ("5365070") or ("4933551") or ("4933551") or ("6214764") or ("6214764") or ("6326631") or		
2	BRS	99784		2003/04/2 4 09:57			
3	BRS	274091	USPAT; US-PGPUB; EPO; JPO; DERWENT		(beam\$1 s ource ray \$1 implan \$8) same (ion\$8 pl asma)		Truncatio n overflow.
4	BRS	54330	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/2 4 09:57	(315/\$7). ccls.		
5	BRS	59737	USPAT; US-PGPUB; EPO; JPO; DERWENT		accelerat \$3 and decelerat \$3		

	Type	Hits .	DBs	Time Stamp	Search Text	Comments	Error Definitio n
6	BRS	678	USPAT; US-PGPUB; EPO; JPO; DERWENT	2003/04/2 4 10:57	((250/\$7).ccls.) and ((beam\$1 source ra y\$1 impla n\$8) same (ion\$8 pl asma)) and (accelera t\$3 and decelerat \$3)		